

TECHNICAL BULLETIN

TAP148

NISSAN PATROL GQ/GU RADIUS ARM TO CHASSIS RUBBER BUSHINGS



If your Patrol Radius Arm to Chassis Bushings are showing wear characteristics as illustrated in the pics opposite, it could be due to a number of reasons.

- 1.** The Durometer of the rubber replacement bushing is too soft - rectified by fitting Roadsafe rubber bushings S0500R in 65 duro
- 2.** If the vehicle has over 2" lift the angle of the radius arm will promote excessive pre-load and premature wear of the bushings - rectified by fitting Blackhawk 4X4 Patrol radius arms (RANPBV2).